

REPLACEMENT SHEET

FIG. 2





FIG. 3




TAPERED-WIDTH MICRO-CANTILEVERS AND MICRO-BRIDGES

Robert J. Weber et al.

Attorney Docket 502224, Telephone (312) 616-5600

REPLACEMENT SHEET

FIG. 4



REPLACEMENT SHEET

FIG. 9a




FIG. 9b




FIG. 9c

